

Technical Information

技術通報

Product: iSCAN II Software Cartridge

Part No.: iSCAN II HONDA

Version: V1.01 SP1

Description: Version update notes

Date: 2008/10/02	From: AUTOLAND SCIENTECH Taiwan	Page: 1/1
-------------------------	--	------------------

V1.01 upgrade to V1.01 SP1

1. All models, SRS system, improve Fault Code displaying problem
2. All models, EPS system, improve Clear Fault Code function